## RATERMANN MANUFACTURING, INC.

MSDS Name: Sherlock Leak Detector Type CG

Date Prepared: 010207

Part Number: LD-CG-5GAL-R

Section 1: Manufacturer's Name

Ratermann Manufacturing, Inc.

**601 Pinnacle Place** 

Livermore, CA 94550

Section 2: Hazardous Ingredients/Identity Information

Non-hazardous per 29 CFR part 1910 subpart Z

HMIS (0=minimal; 1=slight; 2=moderate; 3=serious; 4=severe)

Health: 1

Reactivity: 0

Flammability: 0

Section 3: Physical/Chemical Characteristics

Boiling Point: 212 F (100 C)

Vapor Pressure (mm Hg.): 17.54

Vapor Density (AIR=1): 1.1832

Solubility in Water: 100%

Specific Gravity (Water=1): 1.006

Phone: 800-264-7793

Melting Point: N/A

**Evaporation Rate (Water=1): 1** 

Appearance and Odor: Blue, Clear, Citrus Fragrance

Section 4: Fire and Explosion Hazard Data

Flash Point: None (TCC)

Extinguishing Media: N/A

Special Fire Fighting Procedures: N/A

Unusual Fire and Explosion Hazards: None

**Section 5: Reactivity Data** 

Stable

**Incompatibility: None** 

Hazardous Decomposition or Byproducts: None

Hazardous Polymerization: Will not occur

Section 6: Health Hazard Data

**Routes of Entry: Ingestion** 

Health Hazards: N/A

Carcinogenicity: N/A

Symptoms of Exposure: N/A

Medical Conditions Aggravated by Exposure: None determined

Emergency and First Aid Procedures: Ingestion: Empty stomach and see physician

Eye and Skin Contact: Flush with water

Section 7: Precautions for Safe Handling and Use

Released or Spilled Material: Wipe with absorbent material placing rags in a disposable

container, complete clean-up with water

Waste Disposal Method: Dispose of product in accordance to local, county, state, and

federal regulations

Handling and Storing Precautions: Store in a dry place above 32F, cap tightly to prevent evaporation

Other Precautions: Do not ingest, spray in eyes, or contact with skin

**Section 8: Control Measures** 

Respiratory Protection and Ventilation: None

Protective Wear: Gloves (non-absorbent), Eyes (goggles), Protective Apron

Work/Hygienic Practices: Observe all safe handling practices